




AUV & ATUV SERVICE PUMPS WITH TWO-FLAT SHAFT

In the continuous improvement process of products, Suntec has changed tolerance of its two-flat shaft.

Therefore starting from July 1st, 2020, all pumps will be produced with a two-flat shaft having a diameter of 5.95mm, with a tolerance of ± 0.05 mm.



Affected pumps are listed below:

- AUV 47 L 9877 6P0700
- AUV 47 R 9876 6P0700
- AUV 47 L 9877 6P0700I
- AUV 47 R 9876 6P0700I
- ATUV 45 L 9860 6P0700
- ATUV 45 R 9861 6P0700
- ATUV 45 L 9860 6P0700I
- ATUV 45 R 9861 6P0700I

SUNTEC draws the attention of its customers to the use of used couplings with two-flat shaft. In order to ensure that the pump is still driven by the motor, SUNTEC recommends to replace the coupling if it shows any signs of wear.



Data sheets for AUV and ATUV pumps have been updated and can be found on our website: www.suntec.fr